

BELZONA RESTORES AND PROTECTS GATE VALVE

ID: 6421



PROBLEM

Strong corrosion and erosion on the inner surfaces of all 3 gate valves.

APPLICATION SITUATION

Three large gate valves for water transport from the local dam to the production area.

APPLICATION METHOD

The application was carried out according to Belzona Know-How System Leaflet CEP-1 and CEP-3. The internal welds, pitting and damage were filled with Belzona 1311 then two coats of Belzona 1341 were applied.

BELZONA FACTS

Restoration of 3 valves was carried out within three days, which saved the customer time and money and also eliminated the need to buy new valves. Two months after the restoration of the gate valves, the client protected several pipes and elbows in the water supply, the client now had complete restoration and protection of the whole water system. The client has reported that all equipment and repairs are still in good working condition.

INDUSTRY

Mining & Quarrying

LOCATION

Copper Mining Company, Bulgaria

APPLICATION DATE

April, 2015

PRODUCTS

Belzona 1311 (Ceramic R-Metal)
Belzona 1341 (Supermetalgilde)

SUBSTRATE

Carbon Steel

PHOTOS

1. General view of the valve before repair
2. After blasting and flange masking
3. 1st coat of Supermetalgilde applied
4. Final view of the completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

