

BELZONA REBUILDS WORN STONE STEPS

ID: 6425



PROBLEM

All the stone steps had become badly worn, uneven and sloping towards the front. This was a safety hazard. Due to the construction of the stone steps, it was not possible to repair with other traditional methods.

APPLICATION SITUATION

Badly worn stone steps.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1. Wooden formers were installed to help level the steps evenly.

BELZONA FACTS

The application was done during Normal working hours closing only parts of the school, The other option was to remove and change the stone stairs and to do this they would have had to close the school during the construction period and would have been far more costly than the Belzona option.

INDUSTRY

Buildings & Structures

LOCATION

Prestigious school, Floriana, Malta

APPLICATION DATE

December 2016

PRODUCTS

Belzona 4111 (Magma Quartz)

SUBSTRATE

Stone

PHOTOS

1. Badly worn stone steps
2. Cleaned and Wooden formers installed
3. Steps filled up and leveled with Belzona 4111
4. Finished Job

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

