

BELZONA RECLAIMS DAMAGED BOWLING ALLEY SIDEPLATE

ID: 645



PROBLEM

This damage if not repaired would damage customer bowling balls and lead to loss of sanctioning and income.

APPLICATION SITUATION

Damaged side plate on the pin deck

APPLICATION METHOD

The method used was similar to rebuilding pitting corrosion on vertical vessel walls, a modified Belzona Know-How System Leaflet TCC-5.

BELZONA FACTS

The customer had tried other non-traditional methods such as body filler and drywall mud all unsuccessful.

INDUSTRY

Buildings & Structures

LOCATION

Bowling Centre, Calgary, Alberta, Canada

APPLICATION DATE

November 2005

PRODUCTS

Belzona 8111 (Mouldable Wood)

SUBSTRATE

Hardwood maple slabs

PHOTOS

1. Damaged hardwood slab, 3/4-inch deep
2. First layer of Belzona 8111 applied
3. Final layer of Belzona 8111 after sanding
4. Kick plate reinstalled over damaged area

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

