

BELZONA LINES NEW BUILD DESALTER WITH BELZONA 1391T

ID: 6454



PROBLEM

Newly fabricated vessel which was required to have an internal protective coating.

APPLICATION SITUATION

Operating Temperature Min/Norm/Max:20/58/70 , Service /Crude Oil + Water + Sour Gas and specified with Belzona internal lining and nozzle insert.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5 and TCC-16b . Preformed nozzle inserts were created and bonded into small diameter nozzles to ensure continuity of protection.

BELZONA FACTS

Using the Belzona internal coating and nozzle inserts solution , the vessel will have a longer service life.

INDUSTRY

Oil & Gas

LOCATION

Iraq

APPLICATION DATE

January 2017

PRODUCTS

Belzona 1391T

SUBSTRATE

Carbon Steel

PHOTOS

- 1.Nozzle Insert
- 2.2nd Coating
- 3.Spark Test
- 4.Final

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

