

BELZONA CURES DAMP WALLS

ID: 6458



PROBLEM

Recurring damp was causing damage to the interior and subsequent remedial works. Several solutions had been tried in the past but they had failed to solve the problem. The cause of the damp was not obvious and after seeking professional advice from several sources, the customer was advised that driving rain was the most likely cause.

APPLICATION SITUATION

Private residence

APPLICATION METHOD

Application carried out in accordance with Belzona system leaflet WPA-1

BELZONA FACTS

It was found that the previous coating had numerous defects that allowed water to become trapped, causing the damp. The flexibility and microporous properties of Belzona 5151 allow moisture to escape while preventing further ingress. Since applying the Belzona 5151 the client has not had any problems.

INDUSTRY

Buildings & Structures

LOCATION

Private Residence, North Yorkshire, UK

APPLICATION DATE

2016

PRODUCTS

Belzona 5151 (Hi-Build Cladding)

SUBSTRATE

Brick

PHOTOS

1. House before application
2. Damage to interior
3. Ineffective existing coating
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA®