

BELZONA REPAIRS BROKEN EDGES OF ENGINE BLOCK

ID: 653



PROBLEM

The edge of the engine block was broken.

APPLICATION SITUATION

Engine block

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet ENC-1.

BELZONA FACTS

Belzona easily repaired the broken edge of the block without heat distortion in only one hour of work.

INDUSTRY

Oil & Gas

LOCATION

Oil production company, Egypt

APPLICATION DATE

September 2005

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Cast Iron

PHOTOS

1. The broken edge of the block
2. Surface preparation
3. Rebuilding the broken edge using Belzona 1111
4. Block was repaired

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

