

BELZONA REPAIR BY ROPE ACCESS

ID: 654



PROBLEM

Damage on Neoprene coating and corrosion in splash zone.

APPLICATION SITUATION

8-inch diameter Neoprene coated Riser Pipe

APPLICATION METHOD

Application carried out in accordance with modified Belzona Know-How System Leaflet VPF-3. Existing Neoprene repaired and coated with Belzona® 2211 and Belzona® 2121. Splash zone protected with Belzona® 5831.

BELZONA FACTS

Belzona systems chosen for their ease of application and Belzona® 5831 specifically for its surface tolerance and ability to cure in wet conditions.

INDUSTRY

Oil & Gas

LOCATION

Offshore Platform, Indonesia

APPLICATION DATE

August 2005

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)
Belzona 2121 (D&A Hi-Coat Elastomer)
Belzona 5831 (ST Barrier)

SUBSTRATE

Carbon steel and Neoprene

PHOTOS

1. Preparation of existing Neoprene
2. Rebuild and coating with Belzona 2211 and Belzona 2121
3. Coating splashing zone with Belzona 5831
4. Complete application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

