

BELZONA RESTORES CORRODED COOLER COVER

ID: 656



PROBLEM

Both the inlet and outlet pipes on the cooler were totally corroded through with large holes in the body of the cover.

APPLICATION SITUATION

Cooler cover

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets HEX-3 & HEX-5.

BELZONA FACTS

Instead of being scrapped Belzona restored this cover, getting it back into service with added protection from future corrosion.

INDUSTRY

Marine

LOCATION

Maritime company, Egypt

APPLICATION DATE

March 2005

PRODUCTS

Belzona 1311 (Ceramic R-Metal)
Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Steel

PHOTOS

1. The cover
2. Rebuilding the division bar completed
3. Rebuilding the inlet and outlet pipes
4. Cover coated to provide overall protection

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

