


BELZONA CATION LINING REPAIR

ID: 658



PROBLEM

The rubber lining of the cation had deteriorated and had been lost in many places.

APPLICATION SITUATION

Cation exchange vessel in the water treatment station.

APPLICATION METHOD

Application was carried out in accordance with modified version of Belzona Know-How System leaflet TCC-3.

BELZONA FACTS

Many other coatings and solutions had failed before the use of Belzona® 2121 which was chosen due to its excellent chemical resistance to the regeneration chemicals and for its excellent adhesion.

INDUSTRY

Oil & Gas

LOCATION

Oil production company , Egypt

APPLICATION DATE

October 2005.

PRODUCTS

Belzona 2121 (D&A Hi-coat Elastomer)

SUBSTRATE

Rubber, and Carbon steel.

PHOTOS

1. General view of the Cation
2. The perished areas inside the cation
3. Surface preparation
4. Belzona 2121 applied

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com


BELZONA®

Copyright © 1952-2026 Belzona International Limited.