

BELZONA BUND SEALING TO ENSURE ENVIRONMENTAL COMPLIANCE

ID: 666



PROBLEM

Legislation non-compliance due to newly constructed bund being porous due to construction materials, concrete base and 9 inch concrete block walls.

APPLICATION SITUATION

Bund floor and walls

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet TCC-15.

BELZONA FACTS

Original condition of bund meant that it failed the Environmental compliance guidelines (PPG 2). Belzona materials were easily applied to give a long term impermeable coating system.

INDUSTRY

Commercial Facilities

LOCATION

Commercial Vehicle Repair Shop

APPLICATION DATE

September 2005

PRODUCTS

Belzona 4141 (Magma-Build)
Belzona 4131 (Magma-Screed)
Belzona 5231 (SG Laminate)

SUBSTRATE

Concrete

PHOTOS

1. Porous bund floor and side wall
2. Introduction of wall to wall fillets
3. Wall penetrations sealed and fillet complete
4. Finished job

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA