

# BELZONA REPAIRS LARGE HYDRAULIC RAM

ID: 668



## PROBLEM

Many years in service had caused large vertical gouges to be worn into the ram

## APPLICATION SITUATION

Large Hydraulic Ram

## APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-3.

## BELZONA FACTS

Belzona was the only method of repair available for such a ram and without it the ram would have had to have been replaced. The application was completed for only 400 Euros, a tiny fraction of the cost of a new ram which would have had a lead time of more than 4 weeks taking a large amount of this mill off line.

## INDUSTRY

General Industry

## LOCATION

Hot Roll Mill for Steel Sheets, Macedonia

## APPLICATION DATE

October 2005

## PRODUCTS

Belzona 1221 (Super E Metal)

## SUBSTRATE

Steel

## PHOTOS

1. Surface preparation
2. Ready for application of Belzona
3. Finished repair

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

