


BELZONA STOPS WINDOW LEAKS

ID: 670


1



2



3



PROBLEM

The bottoms of the windows had almost imperceptible openings allowing wind blown water to enter and travel to the entry canopy staining the ceiling tile.

APPLICATION SITUATION

Persistent leaks for several years. Repairs attempted by many people had been unsuccessful.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-3.

BELZONA FACTS

The current director of facilities had used Belzona® 3111 over 20 years ago to stop leaks around a chimney and it is still leak free, so the customer had every confidence in the chosen solution.

INDUSTRY

Buildings & Structures

LOCATION

Community College, St. Charles, Missouri
USA

APPLICATION DATE

August 2005

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Concrete and steel

PHOTOS

1. View of windows above entry canopy.
2. Close up of the problem and start of the repair.
3. Finished repair.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

