

BELZONA CEMENT HOPPER FLANGE REPAIR

ID: 673



PROBLEM

Failure of the rubber gasket allowed cement to fall from the hopper when it was being emptied.

APPLICATION SITUATION

Cement hopper flange

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SOS-10b.

BELZONA FACTS

This large hopper was full of cement so it was not possible to dismantle the flange and change the gasket, therefore, the Belzona solution of sealing the flange again in-situ was the only quick and cost effective solution.

INDUSTRY

Cement

LOCATION

Cement Works, Usje, Macedonia

APPLICATION DATE

August 2004

PRODUCTS

Belzona 1221 (Super E-Metal)

SUBSTRATE

Steel

PHOTOS

1. Application situation
2. During application of Belzona
3. Finished application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

