

BELZONA REBUILDS NON-SLIP SAFETY SYSTEM FOR INDOOR POOL AREA

ID: 682



PROBLEM

The tile surface was extremely slippery so customer had to use special non-slip mats to cover the walk areas. Non-slip mats did not give a good appearance to the atmosphere and smelled.

APPLICATION SITUATION

Tiled floor around Health Club pool area at the hotel Chain.

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet FPA-8. All grout lines running across the path of travel were saw cut with a diamond saw to remove the grout and create a space for the Belzona 4111. After vacuuming, the grout lines were masked off. After conditioning all grout lines with Belzona 4911, a standard Belzona 4111 mix was laid over the grout lines and finished flush with the tape. Dry 4111 Aggregate was then sprinkled over the area and the tape removed.

BELZONA FACTS

The customer was not happy with the non-slip mats as these detracted from the overall appearance of the area. The carpets would also start smelling which necessitate frequent replacement. Belzona solution was a clean and long lasting solution without changing the appearance of the floor, the customer was happy.

INDUSTRY

Buildings & Structures

LOCATION

Whistler, BC, Canada

APPLICATION DATE

November 2003

PRODUCTS

Belzona 4111 (Magma-Quartz)

Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Ceramic tiles

PHOTOS

1. View of Whistler Fairmont Resort Hotel
2. A general view of the Health Club showing the floor mats in place
3. When the product had cured, the area was swept with a broom and vacuumed.
4. View of completed application covering approximately 700 sq.ft

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

