

BELZONA PROTECTS CEMENT WORKS GEARBOX HOUSING

ID: 689



PROBLEM

Poor adhesion of old non-Belzona coating.

APPLICATION SITUATION

Gear box housing

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-15.

BELZONA FACTS

Belzona's quick and effective solution was chosen for its ease of application and immediate availability. Very short down time meant that the customer saved a good deal of time and money.

INDUSTRY

General Industry

LOCATION

Cement Works, Usje, Macedonia

APPLICATION DATE

April 2005

PRODUCTS

Belzona 5811 (Immersion Grade)

SUBSTRATE

Steel

PHOTOS

Application situation The extent of the problem Prepared surface Finished application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.