

BELZONA REPAIRS ASH SCREW CONVEYOR BEARINGS

ID: 690



PROBLEM

Severe wear due to dusty working environment.

APPLICATION SITUATION

Friction Bearings on Ash Screw Conveyor

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-9.

BELZONA FACTS

The bearings were made of grey iron and were lasting just 3-4 weeks. Following the application of Belzona® 1131 the bearings were lasting 3-4 months thus saving down time as the bearings needed replacing less often.

INDUSTRY

General Industry

LOCATION

Cement Works, Usje, Macedonia

APPLICATION DATE

September 2004

PRODUCTS

Belzona 1131 (Bearing Metal)

SUBSTRATE

Steel

PHOTOS

1. Application situation
2. Worn friction bearing
3. Repaired bearings
4. Finished application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

