

BELZONA PROVIDES LONG TERM PROTECTION IN HIGH TEMPERATURE SULPHUR

ID: 695



PROBLEM

Sulphur at 118-128°C was causing high levels of corrosion.

APPLICATION SITUATION

Sulphur pit internal equipment

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets VPF-2.

BELZONA FACTS

Initial application was done as a test. This application was still performing well four years later to the customers shock and delight. Since this initial application lids, pipework, viewports, manways, coil legs and pump externals have all been coated.

INDUSTRY

Oil & Gas

LOCATION

Oil Refinery, United Kingdom

APPLICATION DATE

1997

PRODUCTS

Belzona 1591 (Ceramic XHT)

SUBSTRATE

Carbon Steel

PHOTOS

1. Pipes ready for application
2. Brush application of Belzona 1591
3. Coated pipes

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

