

BELZONA WEATHERPROOFS AIRPORT FIRE STATION ROOF

ID: 696



PROBLEM

This fire station roof was leaking and the local airport authority wanted to repair it and extend its life, rather than a full replacement.

APPLICATION SITUATION

Airport fire station roof

APPLICATION METHOD

Application was carried out in accordance with Belzona® System Leaflet RPA-1

BELZONA FACTS

The unusual construction of this roof posed a problem for other roofing systems. Belzona was chosen as the solution, as the alternative was to completely replace the roof. 2 years on and the application is still in perfect condition.

INDUSTRY

Buildings & Structures

LOCATION

Airport, UK

APPLICATION DATE

May 2003

PRODUCTS

Belzona 3131 (WG Membrane)

SUBSTRATE

Concrete

PHOTOS

1. Roof to be coated
2. The roof after cleaning and surface preparation
3. Coated roof
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

