

BELZONA SEALS INSULATOR LEAKS

ID: 702



PROBLEM

Seal within insulators eroded and as a result oil leakage began to occur.

APPLICATION SITUATION

Power Line Insulators

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How Leaflet GSS-3.

BELZONA FACTS

Belzona products have been used for many of these types of sealing applications with tremendous success.

INDUSTRY

Power

LOCATION

Power Plant, British Columbia, Canada

APPLICATION DATE

August 2003

PRODUCTS

Belzona 2121 (D&A Hi-Coat Elastomer)

SUBSTRATE

Porcelain and Aluminum

PHOTOS

Surface preparation in progress
Surface preparation by grit blasting completed
Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

