

BELZONA SEALS SF6 LEAKS AT HYDROELECTRIC POWER STATION

ID: 705



PROBLEM

SF6 gas was leaking from the joints of the system requiring regular refilling.

APPLICATION SITUATION

SF6 gas pipe

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet GSS-4.

BELZONA FACTS

This application has been in service for many years with only minor repairs required. TOTAL TIME IN SERVICE - 13 YEARS.

INDUSTRY

Power

LOCATION

Hydroelectric Power Plant, British Columbia, Canada

APPLICATION DATE

1993

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Steel

PHOTOS

1. Belzona 2211 was injected into the gap between the 2 flanges.
2. Application shown in #1 completed.
3. Another flange sealed.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

