

BELZONA GLAND HOUSING REBUILD

ID: 720



PROBLEM

Gland housing of the pump was badly worn and damaged due to mechanical failure.

APPLICATION SITUATION

Split casing water pump.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-2.

BELZONA FACTS

Belzona reformed gland housing back to original dimensions without heat and was completed in one day.

INDUSTRY

Power

LOCATION

Power plant , Egypt.

APPLICATION DATE

October 2006.

PRODUCTS

Belzona 1311 (Ceramic R-Metal)

SUBSTRATE

Cast Iron.

PHOTOS

1. The damaged gland housing
2. Preparing the housing
3. Reforming the housing to its original dimensions
4. Repair completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA