

BELZONA HELPS SWEET MANUFACTURER AGAIN AFTER 8 YEARS

ID: 737



PROBLEM

The Belzona coating, applied 8 years previously, was still in good condition and had only suffered some discolouration. The client, however, wanted to apply a fresh coat of Belzona.

APPLICATION SITUATION

Mixing tank

APPLICATION METHOD

The Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

BELZONA FACTS

The client was so pleased that the original Belzona coating lasted 8 years that they once again contacted Belzona to re-coat the machine.

INDUSTRY

General Industry

LOCATION

Sweet Manufacturer, Belgium

APPLICATION DATE

September 2005

PRODUCTS

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Steel & Belzona® 1321

PHOTOS

1. 8-year-old Belzona 1321 coating
2. Another view of 8-year-old Belzona 1321 coating
3. New Belzona 1321 coating
4. Coated hatch

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

