

CLASSIC PUMP REFURBISHMENT WITH BELZONA

ID: 738



PROBLEM

Erosion/corrosion from constant water flow within the pump caused erosion in critical parts of the housing.

APPLICATION SITUATION

Pump Housing

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet CEP-2 & CEP-5.

BELZONA FACTS

Belzona was chosen because the customer had had numerous good experiences with Belzona on previous applications in pumps.

INDUSTRY

General Industry

LOCATION

Copper Manufacturer, Belgium

APPLICATION DATE

November 2005

PRODUCTS

Belzona 1111 (Super Metal)

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Steel

PHOTOS

1. Rebuilding profiles underway
2. Another view of profiles
3. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

