

# BELZONA MANWAY OPENING

ID: 74



## PROBLEM

Opening on chemical tank was corroded to the point where a good seal was not possible.

## APPLICATION SITUATION

Manway opening on chemical storage tank.

## APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet TCC-10.

## BELZONA FACTS

For only \$128 in Belzona® 1111 (Super Metal), downtime and expensive welding was averted. The repair has held for many years, and is still in perfect condition.

## INDUSTRY

Chemical & Petrochemical

## LOCATION

Petroleum Refinery in Texas

## APPLICATION DATE

1991

## PRODUCTS

Belzona 1111 (Super Metal)

## SUBSTRATE

Stainless Steel

## PHOTOS

1. Surface preparation performed with the repair area taped off.
2. Manway rebuilt.

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured  
under an ISO 9001 Registered  
Quality Management System.

[www.belzona.com](http://www.belzona.com)

