


BELZONA REPAIRS A VERY LARGE PUMP HOUSING

ID: 745



PROBLEM

Water infiltration between joint of metal and concrete

APPLICATION SITUATION

Large cooling water pump housing

APPLICATION METHOD

The application was carried out in accordance with a modified Belzona Know-How System Leaflet CEP-5.

BELZONA FACTS

Other solutions were considered implausible by the client who was delighted when Belzona® came up with a solution

INDUSTRY

Power

LOCATION

Power Plant, France

APPLICATION DATE

July 2002

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Steel and Concrete

PHOTOS

1. Application Situation
2. Cleaning
3. Application of Belzona 1111 (Super Metal)

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

