

POSITIVE FEEDBACK ON BELZONA APPLICATION OF A SECONDARY CLARIFIER

ID: 7465



PROBLEM

The secondary clarifiers at the Water Pollution Control Center were pitted and deteriorated due to chemical attack from the biological treatment process.

APPLICATION SITUATION

The clarifiers were covered in algae and debris, creating a particular problem during the summer season when the crew usually works on the maintenance program.

APPLICATION METHOD

The tank was power washed and allowed to dry. Pits, cracks or holes were conditioned with Belzona 4911 and then filled with Belzona 4131 using a trowel. Once repaired, Belzona 5811 was applied to the entire internal part of the tank with rollers and brushes.

BELZONA FACTS

Belzona helped get the tank back in production, helping the entire city of Sarnia. After 6 years, we received feedback from the Maintenance Mechanic of the facility: "Belzona 5811 has been holding very well and will contact the city about budget to move forward to coat the rest of the secondary tanks with Belzona solutions". A second inspection was carried out in April 2024 and the coating is still holding well and protecting the weirs

INDUSTRY

Water / Wastewater

LOCATION

Water and Wastewater Treatment Plant, Ontario, Canada

APPLICATION DATE

October, 2011

PRODUCTS

Belzona 4131 (Magma-Screed) Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

