

BELZONA PROTECTS OF 10 " AND 3 " VALVES ON THE COAST

ID: 7468



PROBLEM

Corrosion problem on 10" valve bolts and several 3" flanges.

APPLICATION SITUATION

Valves and flanges on the coast exposed in a corrosive environment.

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet GSS-11. The Belzona protection system was applied by brush without the installation of plastic caps. This does not affect the corrosion resistance of the system.

BELZONA FACTS

The cold-applied, Belzona system has been chosen in preference to a thermoplastic, hot-applied protection system. The corrosion protection offered by the Belzona 8411/3411 system is ideally suited to encapsulating equipment located in this coastal environment.

INDUSTRY

Oil & Gas

LOCATION

Petroleum Terminal, Gabon

APPLICATION DATE

March 2017

PRODUCTS

Belzona 3411

SUBSTRATE

Steel

PHOTOS

1. Surface preparation 2. Application of the first beige layer of Belzona 3411 in progress 3. Application of the second grey layer of Belzona 3411 4. Application of the Belzona 3411 on the 3" flanges

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

