


BELZONA SUPERWRAP II PROTECTS UNDERGROUND PIPELINE

ID: 7471



PROBLEM

The pipe external wall had corroded due to the long-term humid environment. Pitting corrosion had led to significant wall thinning.

APPLICATION SITUATION

Oil pipeline buried under 1.5 metre depth.

APPLICATION METHOD

The application was carried out by a validated installer following the specific design generated for this application.

BELZONA FACTS

This Belzona SuperWrap II application presented an effective and low-cost repair solution. Rather than expensive and time-consuming replacement of the whole pipeline, the Belzona SuperWrap II application required no hot work and was completed rapidly and with reliable results.

INDUSTRY

Chemical & Petrochemical

LOCATION

Refinery, Shaanxi, China

APPLICATION DATE

July 2016

PRODUCTS

Belzona 1161 (Super UW Metal)
Belzona SuperWrap II

SUBSTRATE

Carbon steel

PHOTOS

1. Severe corrosion in the thinned-wall
2. Surface preparation underway
3. Application of Belzona SuperWrap II
4. Application completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

