

BELZONA KEEPS THE TANK AFLOAT!

ID: 7494



PROBLEM

The original coating had failed in most areas. Pitting on the bottom head and on the shell manway was of particular concern.

APPLICATION SITUATION

Floatation tank operating at 90C, in contact with produced water.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

BELZONA FACTS

Belzona 1391T has been selected for its corrosion resistance in an immersed environment at high temperatures, offering long term protection for the oil operator.

INDUSTRY

Oil & Gas

LOCATION

Offshore oil production platform, Gabon

APPLICATION DATE

March 2017

PRODUCTS

Belzona 1391T

SUBSTRATE

Carbon Steel

PHOTOS

1. View of the tank
2. First coat application completed on the shell
3. Second coat application in progress
- 4- Second coat application completed on the inner part of the tank

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

