


PARKS AND RECREATION RESTROOM FLOOR COATED WITH BELZONA

ID: 7505



PROBLEM

Customer has numerous restrooms in public areas that are porous and cannot be disinfected efficiently.

APPLICATION SITUATION

Rest area needed to be sealed to allow cleaning and disinfecting of public access area. Porous concrete can harbor biological growth.

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona System Leaflet FPA-3. The floor was ground with diamond grinders. Within the overcoat windows two full coats of Belzona 5811 were applied.

BELZONA FACTS

The hard sealed surface allows cleaning crews to clean the restroom much easier, saving man hours and chemical use. Applying the Belzona coating has made the public access safer, cleaner and more pleasant.

INDUSTRY

Buildings & Structures

LOCATION

Montana, USA

APPLICATION DATE

May 2017

PRODUCTS

Belzona 5811 (Immersion Grade)

SUBSTRATE

Concrete

PHOTOS

1. Performing floor grinding preparation
2. Surface edge and floor grinding complete
3. Belzona 5811 application complete

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

