

PROTECTING HVAC DUCTWORK WITH BELZONA

ID: 7534



PROBLEM

Solution required to seal and protect weathered ductwork insulation.

APPLICATION SITUATION

Insulated heating and ventilation ductwork on a university roof.

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet VPF-12.

BELZONA FACTS

Belzona 3211 offers outstanding protection from the elements, including UV exposure. It is micro-porous and will prevent liquid from penetrating through it while allowing any moisture to evaporate, so maintaining thermal efficiency and reducing CUI. This application was photographed in 2017, after 14 years in service. Still in perfect condition.

INDUSTRY

Heating, Ventilation & Air Conditioning

LOCATION

France

APPLICATION DATE

2003

PRODUCTS

Belzona 3211 (Lagseal)

SUBSTRATE

Various insulation materials

PHOTOS

1. Damaged insulation 2. Close up of the damage 3. Belzona repair after 14 years in service 4. Belzona repair after 14 years in service

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.