

BELZONA SAVES UNIVERSITY LIBRARY FROM WATER INGRESS

ID: 7547



PROBLEM

Water ingress was discovered resulting from failure of the sealing materials between the glazed units, caused by UV attack and constant movement due to thermal expansion.

APPLICATION SITUATION

Long stretch of roof lights over library allowing natural light into the building

APPLICATION METHOD

The application was carried out in accordance with Belzona System Leaflet RPA-3.

BELZONA FACTS

The client required a quick, safe and cost effective solution to the water ingress issues. There was the potential for slips on wet floors, water damage to library books and electrical equipment. Removing and replacement of the sealant could have resulted in damaged glazed units, additional time, costs and the danger of falling glass. The work was carried out very successfully over a 15 day period causing minimal disruption and saving the client substantial costs.

INDUSTRY

Buildings & Structures

LOCATION

Library at a Manchester University

APPLICATION DATE

2014

PRODUCTS

Belzona 3121 (MR7)

SUBSTRATE

Glass, Metal

PHOTOS

1. Overview of the units
2. Close up of the damaged area
3. Internal view
4. Completed application with Belzona 3121 in place

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

