

BELZONA PROTECTS FLANGES FOR GAS WORKS

ID: 7554



PROBLEM

The Customer required a solution that would protect the flange from corrosion whilst still allowing access for inspection at a later date.

APPLICATION SITUATION

A section of pipework had an exposed flange that was deemed to be susceptible to corrosion.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet GSS-11.

BELZONA FACTS

The Belzona solution allows the flange to be protected and then accessed when required for maintenance or inspection. Traditional painting of the flange would leave it inaccessible and may not completely encasulate the flange potentially allowing corrosion to still occur.

INDUSTRY

Oil & Gas

LOCATION

Glasgow, Scotland

APPLICATION DATE

June 2017

PRODUCTS

Belzona 3411 (Encapsulating Membrane)

SUBSTRATE

Mild Steel Flange

PHOTOS

1. Flange with void taped
2. First coat during application
3. First coat applied
4. Second coat applied

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

