

BELZONA REPAIRS CONCRETE FOOTING

ID: 7564



PROBLEM

The footing was damaged by impact, this caused instability on the machine which meant it could not be used.

APPLICATION SITUATION

The concrete footing of a cutting machine in a large workshop.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-9.

BELZONA FACTS

The Belzona concrete reappear allowed the machinery to be back online in only 4 days, compared to the possible 28 day cure time for concrete. The Belzona materials also have greater impact resistance to protect from future damage.

INDUSTRY

Buildings & Structures

LOCATION

Construction company, Slovakia

APPLICATION DATE

2006

PRODUCTS

Belzona 4111 (Magma-Quartz)

SUBSTRATE

Concrete and Steel Reinforcement

PHOTOS

1. Destroyed concrete footing.
2. Belzona 4911 (TX Conditioner) application
3. Repair in progress
4. Belzona 4111 used to rebuild the base

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

