



BELZONA PROTECTS SETTLEMENT TANK

ID: 7565



PROBLEM

Erosion/corrosion damage was affecting the normal operation of the equipment

APPLICATION SITUATION

Damage to the tank and mixing equipment

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC 3.

BELZONA FACTS

The Customer required a fast, high quality solution to repair the basin. Belzona provided an effective solution to not only repair the basin and mixing apparatus, but also protect it in the long term, extending the lifetime. Spraying enabled the application to be completed within the available window.

INDUSTRY

General Industry

LOCATION

Pharmaceutical Company, Slovakia

APPLICATION DATE

2010

PRODUCTS

Belzona 5811 (Immersion Grade)

SUBSTRATE

Steel

PHOTOS

1. Mixing Basin
2. Extent of damage to the basin
3. Blasting of the basin
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

