

BELZONA KEEPS THE COVER ON ANNEALING OVEN

ID: 7566



PROBLEM

The cover had distorted and did not sit correctly on the base and caused a CO2 leakage.

APPLICATION SITUATION

Large annealing oven at a metal manufacturing plant.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet ENC - 7.

BELZONA FACTS

Using the Belzona solution allowed the original equipment to be used as a former, ensuring a perfect fit. Rebuilding in this way also meant the line was back up sooner than expected.

INDUSTRY

Steel & Metal Processing

LOCATION

Metallurgy Company, Slovakia

APPLICATION DATE

2011

PRODUCTS

Belzona 1121 (Super XL-Metal)

SUBSTRATE

Iron

PHOTOS

1. Annealing ovens
2. Surface preparation
3. Belzona 1121 application
4. Cover replaced

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

