

# BELZONA REPAIRS A CAR ENGINE CASING

ID: 7567



## PROBLEM

The freezing winter temperatures had caused excessive movement and a crack in the engine casing.

## APPLICATION SITUATION

Cracked Engine Casing on a government vehicle.

## APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet ENC - 1.

## BELZONA FACTS

Welding this kind of damage would take a lot of time and money. Rebuilding with Belzona 1111 was a faster and more economical solution for the customer.

## INDUSTRY

Transport

## LOCATION

Civil Society, Slovakia

## APPLICATION DATE

2016

## PRODUCTS

Belzona 1111 (Super Metal)

## SUBSTRATE

Iron

## PHOTOS

1. Cracked engine.
2. Crack detection.
3. Surface preparation.
4. Belzona 1111 application with reinforcement tape.

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

Copyright © 1952-2026 Belzona International Limited.

