

BELZONA PROTECTS MIXING TANK

ID: 757



PROBLEM

Customer needed protection on their KMnO₄ (Potassium Permanganate) mixing tank.

APPLICATION SITUATION

During expansion, the large dairy constructed a new water plant to treat their own water (average 400,000 GPD).

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How System leaflet TCC-15.

BELZONA FACTS

Customer choose Belzona based on success of previous applications.

INDUSTRY

Water / Wastewater

LOCATION

Dairy in Oklahoma, USA

APPLICATION DATE

March, 2006

PRODUCTS

Belzona 5811 (Immersion Grade)
Belzona 4111 (Magma Quartz)

SUBSTRATE

Concrete

PHOTOS

1. Bare unprotected mixing tank.
2. Surface prepared and holes patched with Belzona 4111.
3. First coat Belzona 5811 being applied.
4. Final coat Belzona 5811 applied.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

