

BELZONA PROTECTS AGAINST EROSIVE MILLED CORN

ID: 7571



PROBLEM

The pipe was suffering from heavy abrasion from the milled corn.

APPLICATION SITUATION

Pneumatic pipe system for transporting milled corn.

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet SHM-7.

BELZONA FACTS

Welding new wear plates or replacing the pipe section would have kept the equipment offline for too long. The Belzona solution allowed the factory to be back online sooner and proved to be more cost-effective to maintain in the long run.

INDUSTRY

Food & Drink

LOCATION

Starch Factory, Slovakia

APPLICATION DATE

2014

PRODUCTS

Belzona 1812 (Ceramic Carbide FP)
Belzona 9811

SUBSTRATE

Steel

PHOTOS

1. Ready for repair.
2. Belzona 1812 application.
3. Belzona 9811 application.
4. Ready for work.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

