

BELZONA REPAIRS CORRODED PUMP CASING

ID: 7583



PROBLEM

The pump had suffered extensive corrosion.

APPLICATION SITUATION

Horizontal split case centrifugal water pump.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-3 and CEP-5.

BELZONA FACTS

Another similar pump had been coated with Belzona 3 years before and a recent inspection found it to be in an excellent condition. Based on this, Belzona were the Customer's first call to repair this pump.

INDUSTRY

Water / Wastewater

LOCATION

Drinking Water Station, Egypt

APPLICATION DATE

2017

PRODUCTS

Belzona 1311 (Ceramic R-Metal)
Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Cast Iron

PHOTOS

1. Corroded pump casing.
2. After grit blasting.
3. Application of Belzona 1311.
4. Application complete.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

