

CONCRETE BUND RESTORED

ID: 7588



PROBLEM

The acid attack had severely damaged the concrete over time, this lead to the acid not being

APPLICATION SITUATION

Concrete bund on a chemical site for catching 98% Sulphuric Acid spills

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-15.

BELZONA FACTS

Originally was the concrete basement was unprotected. After this Belzona reconstruction was customer very satisfied with resistance of this material.

INDUSTRY

Chemical & Petrochemical

LOCATION

Slovakia, chemical pharmaceutical company

APPLICATION DATE

2016

PRODUCTS

Belzona 4301 (Magma CR1 Hi-Build)
Belzona 4311 (Magma CR1)

SUBSTRATE

Concrete

PHOTOS

1. Damaged concrete basement
2. Surface preparation
3. It was necessary to prepare firm surface
4. After Belzona application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

