

BED PLATE OF PRESSING MACHINE REBUILT WITH BELZONA

ID: 7594



PROBLEM

Hydrochloric acid condensed from the process destroyed the base plate of the pressing machine.

APPLICATION SITUATION

Bed plate of press used to accurately form the thickness of rubber sheet.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet ENC-7. After Belzona 1111 application it was necessary to level the plate by grinding.

BELZONA FACTS

Welding of this damage would take a long time, so rebuilding with Belzona 1111 was much better for customer. It was not first repair like this, first repair was done in 2013 and customer was satisfied with the outcome.

INDUSTRY

General Industry

LOCATION

Rubber producer, Slovakia

APPLICATION DATE

2014

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Steel

PHOTOS

1. Surface preparation
2. Belzona 1111 being applied
3. The plate ready for leveling by grinding

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

