

BELZONA PUMP SEATING REPAIR

ID: 7600



PROBLEM

Corrosion, mechanical damage

APPLICATION SITUATION

After long time operation the pump has worn down seating. Result is a big clearance of the bearing.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet CEP - 2

BELZONA FACTS

Welding of the seating is very difficult, takes a long time. Belzona solution means very good repair and result is that customer uses this Belzona repair also for another pumps.

INDUSTRY

Steel & Metal Processing

LOCATION

Slovakia, metallurgic plant

APPLICATION DATE

2014

PRODUCTS

Belzona 1111

SUBSTRATE

Iron casting

PHOTOS

1. Damaged pump seating
2. Machining of the Belzona 1111
3. Ready for customer

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA