


SLIDE ASSEMBLY WITH BELZONA REPAIR

ID: 7606



PROBLEM

Corrosion accelerated due to the inclusion of water and chemicals within the process

APPLICATION SITUATION

Slide assembly were damaged from corrosion.

APPLICATION METHOD

Application was carried out in accordance with modified Belzona Know-How System Leaflet ENC 7.

BELZONA FACTS

Belzona was chosen because welding takes very long time with risk of the compromising the structural integrity.

INDUSTRY

Steel & Metal Processing

LOCATION

Slovakia, metallurgic producer

APPLICATION DATE

2014

PRODUCTS

Belzona 1311

SUBSTRATE

Steel

PHOTOS

1. Damaged slide assembly
2. Belzona 1311 application
3. All surface were sanded down
4. Support ready to work

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

