

COOLING TOWER COATED WITH BELZONA 5811 BY SPRAY

ID: 761



PROBLEM

Previous coating was coming off before going into service.

APPLICATION SITUATION

Cooling Tower in need of protection from environment. Situated inside building.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet HEX-12. Spray applied with Graco Extreme 68-1 Pump and heated lines with Viscon heater.

BELZONA FACTS

Cost savings will be realized in the life of the coating. Alternative was tried and failed. Belzona was highly recommended based on previous successful applications.

INDUSTRY

Buildings & Structures

LOCATION

Automotive Plant in Southern Ontario

APPLICATION DATE

February, 2006

PRODUCTS

Belzona 5811 (Immersion Grade)

SUBSTRATE

Galvanized Steel

PHOTOS

1. Previous coating easily blasted off.
2. Application Pump made ready.
3. Material spray applied to 700 square feet very quickly.
4. Door closures were also coated and job completed.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

