

BELZONA PROVIDES A SLIDING SURFACE REPAIR ON SEALING RINGS

ID: 7610



PROBLEM

Erosion, corrosion

APPLICATION SITUATION

Sliding surfaces of sealing rings were worn down from rubber sealing.

APPLICATION METHOD

Application was carried out in accordance with modified Belzona Know-How System Leaflet CEP - 02

BELZONA FACTS

Rings are too thin for welding and replacing is very expensive.

INDUSTRY

Steel & Metal Processing

LOCATION

Slovakia, metallurgic plant

APPLICATION DATE

2016

PRODUCTS

Belzona 1311 (Ceramic R-Metal)

SUBSTRATE

Steel

PHOTOS

1. Damaged surface
2. Belzona 1311 application
3. Machining of Belzona 1311 for right diameter
4. Machining of Belzona 1311 for right diameter

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

