

CYCLONE COATING PROTECTION WITH BELZONA

ID: 7611



PROBLEM

Damaged cyclone

APPLICATION SITUATION

Milled corn material suffers and also adheres on the cyclone surface.

APPLICATION METHOD

Application was carried out in accordance with modified Belzona System Leaflet SHM- 13

BELZONA FACTS

Conventional welding to be out of service too long and also it is not long lasting solution.

INDUSTRY

Food & Drink

LOCATION

Slovakia, starch factory

APPLICATION DATE

2011

PRODUCTS

Belzona 1812 (Ceramic Carbide FP)

SUBSTRATE

Steel

PHOTOS

1. Ready for repair
2. Belzona 1812 application
3. Belzona 1812 application detail

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

