

RUBBER COATING REPAIR

ID: 7613



PROBLEM

Damaged existing rubber coating

APPLICATION SITUATION

Customer needed to put to the existing device with rubber coating in new construction.

APPLICATION METHOD

Application was carried out in accordance with Belzona 2111 instruction for use.

BELZONA FACTS

Conventional rubber coating repair is very complicated and takes a long time. Belzona 2111 shows better quality by compared with rubber coating.

INDUSTRY

Food & Drink

LOCATION

Slovakia, starch factory

APPLICATION DATE

April 2021

PRODUCTS

Belzona 2111 (D & A Hi-Build Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. Steel construction
2. Belzona 2111 application
3. Construction in device
4. As the customer finds Belzona 2111 suitable for this application, he repeats other constructions at regular intervals.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

