

CHEMICAL CANALIZATION ENTRY REPAIRED WITH BELZONA

ID: 7617



PROBLEM

Corrosion of the steel frame and damage to the concrete

APPLICATION SITUATION

The concrete was destroyed from chemicals.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC 9

BELZONA FACTS

Main benefit for the customer was time, because all repair was carried in very short time, but also important is resistant again chemicals.

INDUSTRY

Chemical & Petrochemical

LOCATION

Petrochemical company, Slovakia

APPLICATION DATE

2016

PRODUCTS

Belzona 4131 (Magma-Screed)

Belzona 5811 (Immersion Grade)

SUBSTRATE

Concrete / Steel

PHOTOS

1. Chemical canalization entry.
2. Belzona Conditioner application
3. Belzona 4131 application
4. Belzona 5811 in 2 layers

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

