

LARGE STORAGE TANK PROTECTED WITH BELZONA

ID: 7618



PROBLEM

The tank had been in service for twenty years and was suffering extensive corrosion damage

APPLICATION SITUATION

Crude oil storage tank

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC 3 & TCC-5

BELZONA FACTS

Customer needed quick and quality repair. All protection was realized with Belzona 5811. Deep corrosion was rebuilt with Belzona 1111.

INDUSTRY

Chemical & Petrochemical

LOCATION

Petrochemical company, Slovakia

APPLICATION DATE

2015

PRODUCTS

Belzona 5811 (Immersion Grade)
Belzona 1111 (Super Metal)

SUBSTRATE

Steel

PHOTOS

1. Tank after 20 years.
2. Blasting of the basin
3. Visible damages after blasting
4. Belzona 5811 coating applied in 2 layers

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

